



**CENTER 317 Humidity Temperature Meter |
Dew Point, Wet Bulb | Range: -20~60°C ; -
4~140°C | Humidity: 0~99%RH | Dew Point
Temperature: -20~60°C ; -4~140°C**

This Hygrometer measures temperature, humidity, dew point temperature and wet bulb temperature performs as a multi point measuring instrument. It comes with a digital dual display.

Specifications	Details
Range	-20~60°C ; -4~140°C
Humidity	0~99%RH
Dew Point	-20~60°C ; -4~140°C
Accuracy	±0.8°C, 1.6°C ±2.5%RH
Resolution	0.1°C ; 0.1°C ; 0.1%RH
Operating Temperature	-20~60°C ; Humidity: 0~55°C
Storage Temperature	-10~60°C (<70%RH)
Battery	1.5V, size AA battery x 4
Dimensions	210x65x43 mm
Weight	Approx.265g