

Precision Plus high accuracy thermometer



The Precision Plus PT100 thermometer is highly accurate and comes with a 5-point UKAS certificate. The Precision Plus measures temperature from -199.99 to 199.99 °C with a resolution of 0.01 °C and a high accuracy of 0.05 °C. Please keep in mind that the accuracies listed are only for instruments. The on/off, max/min, and display hold buttons are conveniently located on the front of the instrument. The Binder probe socket is located at the top of the instrument and allows for the use of a variety of probes depending on the application. The Precision Plus thermometer has a large, easy-to-read LCD display, an open circuit 'Err' indicator, and a low battery indicator.

Specifications	Details
Range	-199.99 to 199.99Â°C
Resolution	0.01Â°C
Accuracy	Â±0.05Â°C
Battery	3 x 1.5 volt AAA
Battery Life	2000 hours
Display	10mm LCD
Dimensions	25 x 56 x 128mm
Weight	130 grams