

## Gagemaker T562 | 7° X 45° Buttress Series Contact Points | Pitch 1



The pitch diameter of machined parts with 7° X 45° Buttress thread forms is checked using these contact points. For the majority of gauges, two are needed.

| Specifications | Details |
|----------------|---------|
| Pitch          | 1       |

